

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/2NWN (GR 31-2 PAD)

Location ID: 323884

Date: 02/27/2025



Photo # 6082 Entrance to location



Photo # 6090 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/2NWNE (GR 31-2 PAD)

Location ID: 323884

Date: 02/27/2025




Photo # 6083 Location



Photo # 6087 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/2NWNE (GR 31-2 PAD)

Location ID: 323884

Date: 02/27/2025



Photo # 6100 NE corner of location



Photo # 6102 SE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/2NWNE (GR 31-2 PAD)

Location ID: 323884

Date: 02/27/2025



Photo # 6103 SW corner of location



Photo # 6104 NW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/2NWNE (GR 31-2 PAD)

Location ID: 323884

Date: 02/27/2025



Photo # 6110 Ditch needs maintenance



Photo # 6112 Rip Rap needs maintenance

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/2NWNE (GR 31-2 PAD)

Location ID: 323884

Date: 02/27/2025



Photo # 6114 Ditch needs maintenance



Photo # 6118 Ditch/Rip Rap needs maintenance

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/2NWNE (GR 31-2 PAD)

Location ID: 323884

Date: 02/27/2025



Photo # 6121 Rip Rap needs maintenance



Photo # 6145 Ditch needs maintenance