

# Inspection Photos

Loc: 488167

Operator: WAVETECH HELIUM INC

Inspection Date: 2/26/2025

County: CHEYENNE




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial photo facing east toward the construction of the location.





## Inspection Photos



**Photo 2.** Facing east along the access road. Additional topsoil will need to be salvaged along the road.





## Inspection Photos



**Photo 4.** Facing along the east side of the location. Surface roughening has occurred around the perimeter of the location.





## Inspection Photos



**Photo 3.** Facing southwest toward the topsoil pile which has been segregated and stored at the south side of the location.





## Inspection Photos



**Photo 5.** Facing southwest along the topsoil pile which has been segregated and stored at the south side of the location.




**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:488167 | Date: 2/26/2025



## Inspection Photos



**Photo 6.** Facing west toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:488167 | Date: 2/26/2025