

# Inspection Photos

February 27th, 2025

Operator: Simcoe LLC - 10749

Location ID: 312017

Inspection Document #: 714001908

La Plata County, CO

Township: SENE 31 34N 7W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
 Location Name: Fairfield Farms 2, 4  
 Location ID: 312017



**Photo 1.** View of the well pad taken from the access point facing center. Note: location sign is scratched and illegible.

Inspection Photos  
Location Name: Fairfield Farms 2, 4  
Location ID: 312017



**Photo 2.** Interim reclamation areas remain with bare soils and little to no vegetation. Evidence of grazing observed, cattle exclusion fencing may be needed to promote establishment of interim vegetation.

Inspection Photos  
Location Name: Fairfield Farms 2, 4  
Location ID: 312017

2/27/25  
347° N



**Photo 3.** Northwest corner of disturbance that is not reasonably needed for production has not been interim reclaimed.

Inspection Photos  
Location Name: Fairfield Farms 2, 4  
Location ID: 312017

2/27/25  
138° SE



Photo 4. Produced water sign has been updated.

