

Final Reclamation Inspection

February 24, 2025

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC- 8960

Location ID: 423225

Inspection Document #: 697505802

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State Whitetail 44-1
Location ID: 423225



Photo 1. Photo taken from the well location entrance of CR85, facing North. Photo illustrates the culvert has not been removed per Rule 1004.a.



Photo 2. Photo taken from the well location entrance of CR85, facing South. See comments under Photo 1.

Inspection Photos
Location Name: State Whitetail 44-1
Location ID: 423225



Photo 3. Photo taken from the eastern well location access road, facing West. Photo illustrates the well location access road meets Rule 1004 vegetative requirements.

Note- appears that recent vehicle traffic used the access road.



Photo 4. Close up photo taken from a portion of the well location access road where there appeared to be recent vehicle traffic. Photo illustrates the access road has established with perennial grasses- Buffalo grass and Blue grama.

Inspection Photos
Location Name: State Whitetail 44-1
Location ID: 423225



Photo 5. Photo taken from the well location, facing West. Photo illustrates the well location meets Rule 1004 vegetative requirements.



Photo 6. Photo taken from the well location, facing North. See comments under Photo 5.

Inspection Photos
Location Name: State Whitetail 44-1
Location ID: 423225



Photo 7. Photo taken from the well location, facing East. See comments under Photo 5.



Photo 8. Photo taken from the well location, facing South. See comments under Photo 5.

Inspection Photos
Location Name: State Whitetail 44-1
Location ID: 423225



Photo 9. Reference photo taken southeast of the well location, facing South. See comments under Photo 5.