



WELL SITE INSPECTION FORM

SCANNED

WELL NAME John B. Gebauer 1-32 API NUMBER 05 - 121 - 10326
OPERATOR Hibbert Oil Prop PERMIT NUMBER _____
LOCATION NESE 32-2N-53W COUNTY Washington
FIELD _____ INSPECTOR Binkley

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) 4 FAIL(N) _____ DATE 8-3-88 FN _____ FD ☒ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____

TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: 7-17-87 DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES ☒ NO _____ PITS BACKFILLED: YES ☒ NO _____

MATERIAL BURIED: YES ☒ NO _____ NA _____ SITE CLEAN: YES ☒ NO _____

BOND RELEASE OK: YES ☒ NO _____ FED _____ HOLE MARKER: YES _____ NO ☒

DATE OF SAFETY/STATUS INSPECTION 8-3-88

COMMENTS _____
