

**Caerus  
H27NW  
Location ID: 335410**



Feb 28, 2025 at 11:23:04 AM  
+39.499542,-107.755702 ±14.00m  
ECM

**Location**



Feb 28, 2025 at 11:23:25 AM  
+39.499542,-107.755702 ±14.00m  
ECM

**Location**

Caerus  
H27NW  
Location ID: 335410



Location



Location

Caerus  
H27NW  
Location ID: 335410



Location



Staining (master valve grease)

Caerus  
H27NW  
Location ID: 335410



Lack of stabilization/ compaction



Lack of stabilization/ compaction

Caerus  
H27NW  
Location ID: 335410



Lack of stabilization/ compaction



Lack of stabilization/ compaction