

Interim Reclamation and Stormwater Inspection

Date: 02/26/2025

Operator: STRACHAN EXPLORATION INC - 83130

Location ID: 435306

Inspection Document #: 718700139

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Wickstrom 6-4
Location ID: 435306



Photo 1. Trash and debris (tumbleweeds and oily rags) and stained soil observed within the pumpjack shed.



Photo 2. Stained soil and leaking equipment at pumpjack unit.



Photo 3. Stained soil and leaking equipment at pumpjack unit.

Inspection Photos
Location Name: Wickstrom 6-4
Location ID: 435306



Photo 4. Stained soils near wellhead.

Inspection Photos
Location Name: Wickstrom 6-4
Location ID: 435306



Photo 5. No tank labels/placards at day tank.

Inspection Photos
Location Name: Wickstrom 6-4
Location ID: 435306



Photos 6 & 7. It appears that interim reclamation has been performed for areas only needed for production. A vegetative assessment will be performed at a later date during the active growing season to verify interim reclamation regulations and standards and will therefore remain “In-Process”.