

Interim Reclamation and Stormwater Inspection

Date: 02/26/2025

Operator: STRACHAN EXPLORATION INC - 83130

Location ID: 331795

Inspection Document #: 718700141

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Wickstrom 6-5
Location ID: 331795



Photo 1. Southeast corner. Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. A vegetative assessment will be performed at a later date during the active growing season to verify interim reclamation regulations and standards and will therefore remain "In-Process".

Inspection Photos
Location Name: Wickstrom 6-5
Location ID: 331795



Photo 2. Northeast corner of the location; see comments in Photo 1.

Inspection Photos
Location Name: Wickstrom 6-5
Location ID: 331795



Photo 3. Northwest corner of the location; see comments in Photo 1. Debris also pictured, indicated by red arrow.

Inspection Photos
Location Name: Wickstrom 6-5
Location ID: 331795



Photo 4. Southwest corner of the location; see comments in Photo 1.

Inspection Photos
Location Name: Wickstrom 6-5
Location ID: 331795



Photos 5 & 6. Unused equipment near pumpjack unit.

Inspection Photos
Location Name: Wickstrom 6-5
Location ID: 331795



Photo 7. Unused equipment near pumpjack unit.



Photo 8. Stained soil observed at pumpjack unit.

Inspection Photos
Location Name: Wickstrom 6-5
Location ID: 331795



Photo 9 & 10. Trash and debris observed throughout the location.