

Interim Reclamation and Stormwater Inspection

Date: 02/26/2025

Operator: STRACHAN EXPLORATION INC - 83130

Location ID: 429227

Inspection Document #: 718700145

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Photo 1. Northern interim areas. Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. This location is situated within fallow cropland and will therefore remain "In-Process" until it can be inspected again at a later date.



Photo 2. Southern interim areas. Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. This location is situated within fallow cropland and will therefore remain "In-Process" until it can be inspected again at a later date.



Photo 3. Stained soils observed at the pump jack unit.

Inspection Photos
Location Name: Green 1-10
Location ID: 429227



Photo 4. Trash at pump jack unit.



Photo 5. Stained soil observed near pump jack exhaust.