

Inspection Photos
Location: Craig 6-4 SWD
Location ID: 414280, Spill ID 479428
API # 05-073-06391



Photo 1 –Placard at tank battery



Photo 2 – Area where Spill ID 479428 breached containment

Inspection Photos
Location: Craig 6-4 SWD
Location ID: 414280, Spill ID 479428
API # 05-073-06391



Photo 3 – Impacted soils



Photo 4 – Impacted soils

Inspection Photos
Location: Craig 6-4 SWD
Location ID: 414280, Spill ID 479428
API # 05-073-06391



Photo 5 –Impacted soils



Photo 6 – SWD wellhead in building

Inspection Photos
Location: Craig 6-4 SWD
Location ID: 414280, Spill ID 479428
API # 05-073-06391



**Photo 7 – Area where impacts were observed in
Form 19 Document # 402614154**



**Photo 8 – Area where impacts were observed in
Form 19 Document # 402614154**

Inspection Photos
Location: Craig 6-4 SWD
Location ID: 414280, Spill ID 479428
API # 05-073-06391



Photo 9 – Tank Battery

Photo 10 – Unlabeled tanks

Inspection Photos
Location: Craig 6-4 SWD
Location ID: 414280, Spill ID 479428
API # 05-073-06391



Photo 11 – Impacts observed within secondary containment



Photo 12 – Arrow shows area of potential impacts