

Inspection Photos
Location Name: Horsetail 33M -2804
Location ID: 436724



Photo 1 – Signs at Entrance



Photo 2 – Tank Battery

Inspection Photos
Location Name: Horsetail 33M -2804
Location ID: 436724




Photo 3 – Berm is compromised at South End




Photo 4 – Unmarked OOSLAT Risers

Inspection Photos
Location Name: Horsetail 33M -2804
Location ID: 436724



Photo 5 – Tank Battery



Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Horsetail 33M -2804
Location ID: 436724



Photo 7 – Heater Treater




Photo 8 – Unmarked Risers at Flare Site

Inspection Photos
Location Name: Horsetail 33M -2804
Location ID: 436724



Photo 9 – Wellhead



Photo 10 – Pumping Unit

Inspection Photos
Location Name: Horsetail 33M -2804
Location ID: 436724



Photo 11 – Wellhead Sign