

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30NESE

Location ID: 324012

Date: 2/27/2025



Feb 27, 2025 at 13:30:22
5118 Divide Creek Rd
New Castle CO 81647
United States

Location Overview – Photo #06929



Feb 27, 2025 at 13:34:01
5118 Divide Creek Rd
New Castle CO 81647
United States

Location – Photo #06936

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30NESE

Location ID: 324012

Date: 2/27/2025



Location – Photo #06930



Location – Photo #06931

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30NESE

Location ID: 324012

Date: 2/27/2025



Wildlife Entry Hazard – Photo #06932



Lack of Stabilization – Photo #06937

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30NESE

Location ID: 324012

Date: 2/27/2025



Lack of Stabilization – Photo #06939



Insufficient Tracking BMPs – Photo #06940