

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GGU RODREICK-66S91W/31NENW

Location ID: 311685

Date: 2/27/2025



Location – Photo #06964



Location – Photo #06965

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GGU RODREICK-66S91W/31NENW

Location ID: 311685

Date: 2/27/2025



Location – Photo #06968



Lack of Stabilization – Photo #06966

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GGU RODREICK-66S91W/31NENW

Location ID: 311685

Date: 2/27/2025



Lack of Stabilization – Photo #06967



Insufficient Tracking BMPs – Photo #06969