

Final Reclamation and Stormwater Inspection

February 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 462560

Location Name: UPRR 42 PAN AM AE-62N67W-TANK/31NESE

Inspection Document #: 718600271

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: UPRR 42 PAN AM
AE-62N67W-TANK/31NESE
Location ID: 462560



Photo 1. Looking west across location. Two risers remain on location that appear to be associated with the tank battery. one is pictured (red circle). Access road appears to be used for construction and midstream pipeline access.



Photo 2. Looking north across location. Desirable vegetation has established on parts of the location.



Inspection Photos
Location Name: UPRR 42 PAN AM
AE-62N67W-TANK/31NESE
Location ID: 462560



Photo 3. Risers at the north side of location. These risers appear to be associated with KP Kauffman Company INC.



Photo 4. Risers at the northwest part of the location. See Photo 3 comments.



Inspection Photos
Location Name: UPRR 42 PAN AM
AE-62N67W-TANK/31NESE
Location ID: 462560



Photo 5. Tipped over port a let in the northwest corner of location.



Photo 6. T-post and exposed pipe and valve in the southwest corner of location.



Inspection Photos
Location Name: UPRR 42 PAN AM
AE-62N67W-TANK/31NESE
Location ID: 462560



Photo 7. Riser in the middle of location.



Photo 8. Culvert remains in place.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718600271

Inspection Photos
Location Name: UPRR 42 PAN AM
AE-62N67W-TANK/31NESE
Location ID: 462560



Photo 9. Photo 6, pipe and valve (green circle). Photo 7, riser (red circle).

