

Inspection/Audit Photos
Location Name: QB Energy OKAGAWA 4-10 (J4E) Pad
Location ID: 323974



Photo # 9949 From entrance to location



Photo # 9950 Location

Inspection/Audit Photos
Location Name: QB Energy OKAGAWA 4-10 (J4E) Pad
Location ID: 323974



Photo # 9951 Location




Photo # 9952 Location

Inspection/Audit Photos
Location Name: QB Energy OKAGAWA 4-10 (J4E) Pad
Location ID: 323974



Photo # 9953 Location



Photo # 9954 Location

Inspection/Audit Photos
Location Name: QB Energy OKAGAWA 4-10 (J4E) Pad
Location ID: 323974



Photo # 9955 Wellhead sign laying on ground near separator/sign not properly posted