

**KT Resources LLC
Ant Hill Unit 18-43
Location ID: 316341**



Information missing



Leaking equipment. Oily waste and stained soil.

**KT Resources LLC
Ant Hill Unit 18-43
Location ID: 316341**




Faded label



Required information missing

KT Resources LLC
Ant Hill Unit 18-43
Location ID: 316341



Cap missing on riser

Full 6122' Rio Blanco Mar 4, 2025 at 9:58:45 AM ROC 503

EMPACT ANALYTICAL SYSTEMS INC.
365 SOUTH MAIN
BRIGHTON, CO 80601
303-637-0150 www.empactanalytical.com


Meter S/N
15828417
COC 0127535

Station Name AHLL 18-43
Station No. 120275579 Producer 310P
Sec 18 Township 2N Range 96W
Diff 250' Temp Range 0-150° Tube Size 2.066
Static 200# Absolute 11.78 psig

Date	Orifice Plate Size	Meter Test Date	Sample Date
6M 11-29-17	1.250 ✓	11-29-17	
6M 5-15-18	1.250	5-15-18	7-9-18 WH
KB 10-24-18	1.250	10-24-18	10-24-18
KB 5-14-19	1.250	5-14-19	5-14-19
.9932 10-3-19	1.250	10-3-19	10-3-19 KB
1-12-22	1.250	1-12-22	KB

Calibration overdue

**KT Resources LLC
Ant Hill Unit 18-43
Location ID: 316341**



Location from the Southeast entrance



Location from the Northwest

