

Inspection/Audit Photos
Location Name: QB Energy BENZEL 1-9 (I1) Pad
Location ID: 334801



Photo # 543 From entrance to location



Photo # 544 Location

Inspection/Audit Photos
Location Name: QB Energy BENZEL 1-9 (I1) Pad
Location ID: 334801



Photo # 545 Location



Photo # 546 Location

Inspection/Audit Photos
Location Name: QB Energy BENZEL 1-9 (I1) Pad
Location ID: 334801



Photo # 547 Location



Photo # 548 Location

Inspection/Audit Photos
Location Name: QB Energy BENZEL 1-9 (I1) Pad
Location ID: 334801



Photo # 549 Location




Photo # 550 Pneumatic control valve on summit pipeline near meter house has been modified/valve no longer has the ability to close

Inspection/Audit Photos
Location Name: QB Energy BENZEL 1-9 (I1) Pad
Location ID: 334801



Photo # 551 Pneumatic control valve on summit pipeline near meter house has been modified/valve no longer has the ability to close