

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404115865

Date Received:

03/05/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Sanford, Anita

Anita.Sanford@scoutep.com

Christian, Cody

Cody.Christian@scoutep.com

Johnson, Mike

Mike.Johnson@scoutep.com

RangelyRegulatory@scoutep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718100266

Inspection Date: 02/24/2025

FIR Submit Date: 02/27/2025

FIR Status: _____

Inspected Operator Information:

Company Name: SCOUT ENERGY MANAGEMENT LLC

Company Number: 10779

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

LOCATION - Location ID: 315585

Location Name: UNION PACIFIC-62N102W Number: 21SENW County: _____

Qtrqtr: SENW Sec: 21 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.128770 Longitude: -108.852320

FACILITY - API Number: 05-103- -00 Facility ID: 315585

Facility Name: UNION PACIFIC-62N102W Number: 21SENW

Qtrqtr: SENW Sec: 21 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.128770 Longitude: -108.852320

CORRECTIVE ACTIONS:

1 CA# 202749

Corrective Action: Replace cap and remove and properly dispose fluids within containment.

Date: 03/14/2025

Response: CA COMPLETED

Date of Completion: 03/04/2025

Replaced cap and remove and properly disposed fluids within containment. See attached pictures.

Corrective Action:	Comply with Rule 1002.f.(2)F and install or maintain required vehicle tracking control	Date: 03/06/2025
--------------------	--	------------------

Date: 03/06/2025

Date of Completion: 03/04/2025

Tracking controls were installed to stabilize access road and working pad. Weeds were controlled. See attached pictures.

--

Comment:

Print Name: Anita Sanford Signed:

Signed: _____

Date: 3/5/2025 7:05:46 AM

46 website (<http://comawa.com.au>)

Document Number	Description
-----------------	-------------

Total Attach: 2 Files