

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404115933

Date Received:

03/05/2025

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 95960

Name of Operator: WEXPRO COMPANY

Address: P O BOX 45003

City: SALT LAKE CITY State: UT Zip: 84145-0601

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Russell Ferrell

Phone

307-352-7566

Email

russell.l.ferrell@dominionenergy.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 694500765

Inspection Date: 01/31/2025

FIR Submit Date: 02/18/2025

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: WEXPRO COMPANY

Company Number: 95960

Address: P O BOX 45003

City: SALT LAKE CITY State: UT Zip: 84145-0601

#### LOCATION - Location ID: 312903

Location Name: MUSSER, B W-611N97W Number: 5NENE County: \_\_\_\_\_

Qtrqtr: NENE Sec: 5 Twp: 11N Range: 97W Meridian: 6

Latitude: 40.948810 Longitude: -108.307510

#### FACILITY - API Number: 05-081- -00 Facility ID: 100365

Facility Name: B.W. MUSSER 16 Number: \_\_\_\_\_

Qtrqtr: NENE Sec: 5 Twp: 11N Range: 97W Meridian: 6

Latitude: 40.948810 Longitude: -108.307510

### CORRECTIVE ACTIONS:

1 CA# 202554

Corrective Action: The Operator shall ensure that erosion is not compromising the monitoring wells and remain compliant with ECMC Rules; 1002 See attached photos.

Date: 06/01/2025

Response: CA COMPLETED

Date of Completion: 02/25/2025

Operator Comment: Wexpro Company has fixed the erosion issue and will continue to monitor the area around the monitoring wells to make sure erosion does not compromise them. Approval for the SVE wells was in document #402610223, with additional borehole approvals for the project in document numbers' 40272771 and 402714866. A follow up report with WSP's final report of the installation of the monitoring wells and delineation was approved in document number 402976219.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Wexpro Company has fixed the erosion issue and will continue to monitor the area around the monitoring wells to make sure erosion does not compromise them. Approval for the SVE wells was in document #402610223, with additional borehole approvals for the project in document numbers' 40272771 and 402714866. A follow up report with WSP's final report of the installation of the monitoring wells and delineation was approved in document number 402976219.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Russell Ferrell

Signed: \_\_\_\_\_

Title: Assoc. Reclamation Agent

Date: 3/5/2025 8:49:15 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

404116000	Photo
-----------	-------

Total Attach: 1 Files