

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404118538

Date Received:

03/06/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

0 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Victoria Dizghinjili

3038254822

vdizghinjili@kpk.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718600308

Inspection Date: 02/06/2025

FIR Submit Date: 03/04/2025

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 462560

Location Name: UPRR 42 PAN AM AE-62N67W-TANK Number: 31NESE County: _____

Qtrqr: NESE Sec: 31 Twp: 2N Range: 67W Meridian: 6

Latitude: 40.091957 Longitude: -104.924467

FACILITY - API Number: 05-123-00 Facility ID: 462560

Facility Name: UPRR 42 PAN AM AE-62N67W-TANK Number: 31NESE

Qtrqr: NESE Sec: 31 Twp: 2N Range: 67W Meridian: 6

Latitude: 40.091957 Longitude: -104.924467

CORRECTIVE ACTIONS:

1 CA# 202975

Corrective Action: Comply with the reclamation rules to remove all debris, abandoned gathering line risers, and flowline risers, and equipment from closed facilities.

Date: _____

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: Oxy company had a tank battery here, KPK never did. KPK's header that marked in FIR for abandonment is still active and part of consolidation. Other than that little header area, KPK are not responsible nor have the rights to the rest of the location. The porta potty is clearly part of the construction site (has a sign there), not associated

with oil and gas.

ECMC Decision: _____

ECMC
Representative:

2 CA# 202976

Corrective Action: Remove unused equipment. Perform reclamation in accordance with Rule 1004.

Date: _____

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator
Comment: Oxy company had a tank battery here, KPK never did. KPK's header that marked in FIR for abandonment is still active and part of consolidation. Other than that little header area, KPK are not responsible nor have the rights to the rest of the location. The porta potty is clearly part of the construction site (has a sign there), not associated with oil and gas.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: _____

Title: ET

Date: 3/6/2025 12:24:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404118538	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files