

## Inspection Photos

Location Name: WELLS RANCH - USX AA-66N63W/33NESW

Location #: 310413



Photo #1

Wells Ranch - USX AA 33-25 Battery site

Inactive | Shut-down

Wellsite(s), Battery entrance



Photo #2

Wells Ranch - USX AA 33-25 Battery site

Inactive | Shut-down



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: WELLS RANCH - USX AA-66N63W/33NESW

Location #: 310413



**Photo #3**

**Wells Ranch - USX AA 33-25** Battery site

**Inactive | Shut-down**

*Crude oil, produced H2O tank(s): SE corner*



**Photo #4**

**Wells Ranch - USX AA 33-25** Battery site

**Inactive | Shut-down**

*ECD(s), Separator(s)*

;



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: WELLS RANCH - USX AA-66N63W/33NESW

Location #: 310413



Photo #5

Wells Ranch - USX AA 33-25 Battery site

Inactive | Shut-down

Battery sign



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: WELLS RANCH - USX AA-66N63W/33NESW

Location #: 310413

Associated Well(s)	API	Status
1. Wells Ranch - USX AA 33-25	123-26373	TA

### Photo #6

Wells Ranch - USX AA 33-25 Battery site

Inactive | Shut-down

Associated Well(s):

1: Temporarily Abandoned | TA



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources