

Southern Ute N2  
Inspection #714001361  
Date completed 2/28/2025  
Erosion mitigation and seeding



Runoff ditch cleaned out and tank label installed

