

Inspection Photos

Loc: 309517

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 3/6/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309517 | Date: 3/6/2025

Inspection Photos



Photo 2. Facing toward the wellhead which is inside the shed. It appears there is a dripping water leak coming out of the shed.



Inspection Photos



Photo 3. Facing east along the fill slope.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309517 | Date: 3/6/2025