

Inspection Photos

Loc: 309298

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 3/6/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road. It appears recent BMP maintenance was performed along the road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309298 | Date: 3/6/2025

Inspection Photos



Photo 2. Facing southwest at the location..



Inspection Photos



Photo 3. The cut slope has been reseeded and hydromulched.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309298 | Date: 3/6/2025

Inspection Photos



Photo 4. There is a dripping water leak at the wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309298 | Date: 3/6/2025

Inspection Photos



Photo 5. Facing northwest at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309298 | Date: 3/6/2025