

# Inspection Photos

Loc: 308323

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 3/6/2025

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing southwest toward the PW pit which has been dug out to accommodate 2 ft. freeboard.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:308323 | Date: 3/6/2025

## Inspection Photos



**Photo 2.** Facing northwest toward the wellsite.



Inspection Photos



**Photo 3.** Well sign is posted at the meter shed.

