

Inspection Photos

March 5th, 2025

Operator: Simcoe LLC - 10749

Location ID: 325794

Inspection Document #: 714001931

La Plata County, CO

Township: NWSE 22 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

3/5/25
312° NW



Photo 1. View of the well pad from the access point facing center.



Inspection Photos
Location Name: Roger Kelly
Location ID: 325794



Photo 2. Stained soils at pump jack muffler.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09994

Inspection Photos
Location Name: Roger Kelly
Location ID: 325794



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Wildlife covering/BMP at lube tank secondary containment has gaps and is not functioning.

API #: 067-09994

Inspection Photos
Location Name: Roger Kelly
Location ID: 325794



3/5/25
151° SE

