

Inspection Photos

March 5th, 2025

Operator: Simcoe LLC - 10749

Location ID: 333470

Inspection Document #: 714001932

La Plata County, CO

Township: SWNE 35 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Turner Securities A2, A4
Location ID: 333470



Photo 1. View of the well pad from the access point facing center.



API #: 067-08331, 09393

Inspection Photos
Location Name: Turner Securities A2, A4
Location ID: 333470



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Stormwater BMPs in the southern portion of the pad have not been installed properly and are not functioning properly.

API #: 067-08331, 09393

Inspection Photos
Location Name: Turner Securities A2, A4
Location ID: 333470

3/5/25
24° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Eastern interim reclamation area composed of Smooth Brome, Rabbitbrush and Western Wheatgrass.

API #: 067-08331, 09393