

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W/17SESE

Location ID: 335074

Date: 03/4/2025



Photo # 6369 Entrance to location



Photo # 6370 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W/17SESE

Location ID: 335074

Date: 03/4/2025



Photo # 6376 Location



Photo # 6384 NE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W/17SESE

Location ID: 335074

Date: 03/4/2025



Photo # 6385 NW corner of location



Photo # 6386 SW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W/17SESE

Location ID: 335074

Date: 03/4/2025



Mar 4, 2025 at 12:20:33 PM
+39.518855,-108.127399 ±5.36m



Mar 4, 2025 at 12:13:01 PM
+39.519020,-108.127548 ±7.94m

Photo # 6387 SE corner of location

Photo # 6381 Debris

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W/17SESE

Location ID: 335074

Date: 03/4/2025



Photo # 6390 Debris

