

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 03/6/2025



Photo # 6574 Entrance to location



Photo # 6584 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 03/6/2025



Photo # 6575 Location




Photo # 6581 Location



Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 03/6/2025



Photo # 6582 Location



Photo # 6605 Location



Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 03/6/2025



Photo # 6597 SE corner of location



Photo # 6598 SW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 03/6/2025



Photo # 6599 NW corner of location



Photo # 6600 NE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 03/6/2025




Photo # 6587 Tank lacks required labeling/does not comply with CECMC rules