

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, LINDAUER-67S96W/11NENE

Location ID: 334949

Date: 3/5/2025



Location Overview – Photo #07011



Location – Photo #07012



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, LINDAUER-67S96W/11NENE

Location ID: 334949

Date: 3/5/2025



Location – Photo #07017



Location – Photo #07021

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, LINDAUER-67S96W/11NENE

Location ID: 334949

Date: 3/5/2025



Location – Photo #07018



Weathered/Peeling Tank Label – Photo #07019



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, LINDAUER-67S96W/11NENE

Location ID: 334949

Date: 3/5/2025



Weathered Wellhead Sign – Photo #07013



Weathered Wellhead Sign – Photo #07014



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, LINDAUER-67S96W/11NENE

Location ID: 334949

Date: 3/5/2025



Weathered Wellhead Sign – Photo #07015



Weathered Wellhead Sign – Photo #07016



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, LINDAUER-67S96W/11NENE

Location ID: 334949

Date: 3/5/2025



Check Dam BMP Needs Maintained – Photo #07024



Check Dam BMP Needs Maintained – Photo #07025



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, LINDAUER-67S96W/11NENE

Location ID: 334949

Date: 3/5/2025



Check Dam BMP Needs Maintained – Photo #07028



Check Dam BMP Needs Maintained – Photo #07029