

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSE

Location ID: 334932

Date: 3/5/2025



Mar 5, 2025 at 11:28:01
Parachute CO 81635
United States



Mar 5, 2025 at 11:29:25
Parachute CO 81635
United States

Location Overview – Photo #07046

Location – Photo #07050

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSE

Location ID: 334932

Date: 3/5/2025



Location – Photo #07049



Location – Photo #07047

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSE

Location ID: 334932

Date: 3/5/2025



Weathered Battery Sign – Photo #07048



Rill Erosion Cutting Through Lease Road – Photo #07043

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, AMERICAN SODA-67S96W/2SWSE

Location ID: 334932

Date: 3/5/2025



Rill Erosion Cutting Through Lease Road – Photo #07044