

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE


Location ID: 323960

Date: 3/5/2025



Mar 5, 2025 at 11:49:14
De Beque CO 81630
United States

Location Overview – Photo #07052



Mar 5, 2025 at 11:49:41
De Beque CO 81630
United States


Location – Photo #07053

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE

Location ID: 323960

Date: 3/5/2025



Location – Photo #07056



Location – Photo #07054

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE

Location ID: 323960

Date: 3/5/2025



Weathered Battery Sign – Photo #07055



Stored Supplies – Photo #07057

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE

Location ID: 323960

Date: 3/5/2025



Insufficient Erosion Control/Degradation – Photo #07058



Insufficient Erosion Control/Degradation – Photo #07059

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE

Location ID: 323960

Date: 3/5/2025



Insufficient Erosion Control/Degradation – Photo #07060