

Inspection Photos
Location Name: J E Kirkmeyer 1
Location ID: 318799



Pic 1 wellhead / pumpjack

Pic 2 wellhead sign needs to be picked up and re installed