

Inspection Photos
Location Name: Razor 33 CPB
Location ID: 437030



Photo 1 – Tank Battery Sign



Photo 2 – Water Tanks

Inspection Photos
Location Name: Razor 33 CPB
Location ID: 437030



Photo 3 – Flare and ECD



Photo 4 – Tank Battery and LACT

Inspection Photos
Location Name: Razor 33 CPB
Location ID: 437030



Photo 5 – Unmarked Risers



Photo 6 – Compressor

Inspection Photos
Location Name: Razor 33 CPB
Location ID: 437030



Photo 7 – Heater Treater