

Inspection Photos  
Location Name: Leffler 2SD, 33-2  
Location ID: 310076



Photo 1: Wellhead Sign

Photo 2: Wellhead

Inspection Photos  
Location Name: Leffler 2SD, 33-2  
Location ID: 310076



Photo 3: Wellhead Sign

Photo 4: Wellhead

Inspection Photos  
Location Name: Leffler 2SD, 33-2  
Location ID: 310076



Photo 5: Tank Battery Sign

Photo 6: Centralized tank battery

Inspection Photos  
Location Name: Leffler 2SD, 33-2  
Location ID: 310076



Photo 7: Equipment