

# Final Reclamation and Stormwater Inspection

Date: 03/05/2025

Operator: BONANZA CREEK ENERGY OPERATING  
COMPANY LLC - 8960

Location ID: 306047

Inspection Document #: 718700175

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Pronghorn 41-9 Pad  
Location ID: 306047



**Photos 1 & 2.** Taken from the entrance (left; Photo 1) and along the access road (right; Photo 2) of the former location. It appears that reclamation activities have been performed with evidence of desirable vegetation.



Inspection Photos  
Location Name: Pronghorn 41-9 Pad  
Location ID: 306047



**Photos 3 & 4.** Facing north (left; Photo 3) and east (right; Photo 4) from the center portion of the location. It appears that reclamation activities have been performed with evidence of desirable vegetation. Location appears to be progressing towards reclamation standards and regulations.



Inspection Photos  
Location Name: Pronghorn 41-9 Pad  
Location ID: 306047



**Photos 5 & 6.** Facing south (left; Photo 5) and west (right; Photo 6) from the center portion of the location. It appears that reclamation activities have been performed with evidence of desirable vegetation. Location appears to be progressing towards reclamation standards and regulations.