


Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Domestic Tap/GM 44-2

Facility ID: 456935

Date: 3/5/2025



Location – Photo #07032



Location – Photo #07036

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Domestic Tap/GM 44-2

Facility ID: 456935

Date: 3/5/2025



PRV Terminates in Unsafe Manner – Photo #07037



PRV Terminates in Unsafe Manner – Photo #07038