

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESW

Location ID: 324117

Date: 3/5/2025



Location – Photo #07063



Location – Photo #07065

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESW

Location ID: 324117

Date: 3/5/2025



Location – Photo #07066



Unused/Stored Equipment – Photo #07068

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESW

Location ID: 324117

Date: 3/5/2025



Unserviceable Wildlife Netting – Photo #07067



Insufficient Erosion Control – Photo #07069