

Inspection Photos  
Location Name: Pauli 3-7  
API Number: 125-09822



1. Lease sign at well location. Peeling operator sticker noted.



2. View of wellhead.

Inspection Photos  
Location Name: Pauli 3-7  
API Number: 125-09822



3. Well location overview.



4. Lease sign at remote gathering location. Peeling operator sticker noted.

**Inspection Photos**  
**Location Name: Pauli 3-7**  
**API Number: 125-09822**



**5. Meter calibration log inside meter box. Last calibration dated 9-15-23.**



**6. View of Content/Quantity/Hazard sign at produced water tank. Part of sign is unreadable and operator sticker is peeling.**

Inspection Photos  
Location Name: Pauli 3-7  
API Number: 125-09822



7. Overview of produced water tank. Note overflow line left side of tank.



8. Closer view of overflow line that crosses top of tank berm.

**Inspection Photos**  
**Location Name: Pauli 3-7**  
**API Number: 125-09822**



**9. View of approximately 15' X 15' overflow pit located at gathering/production facility.**



**10. Remote gathering location overview.**