

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/28SWNW

Location ID: 335129

Date: 3/6/2025



Location Overview – Photo #07101



Location – Photo #07103

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/28SWNW

Location ID: 335129

Date: 3/6/2025



Location – Photo #07104



Location – Photo #07106

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/28SWNW

Location ID: 335129

Date: 3/6/2025



Lack of Stabilization – Photo #07102



Insufficient Tracking BMPs – Photo #07107