

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/33NENW

Location ID: 335287

Date: 3/6/2025



Location Overview – Photo #07115



Location – Photo #07119

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/33NENW

Location ID: 335287

Date: 3/6/2025



Location – Photo #07117



Location – Photo #07116

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/33NENW

Location ID: 335287

Date: 3/6/2025



Lack of Stabilization – Photo #07118



Lack of Stabilization – Photo #07120

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MOBIL-66S95W/33NENW

Location ID: 335287

Date: 3/6/2025



Insufficient Tracking BMPs – Photo #07121