

Inspection/Audit Photos

Location Name: QB Energy SHAEFFER 31-6 (H-36) Pad

Location ID: 334904



Photo # 1950 From entrance to location




Photo # 1951 Location

Inspection/Audit Photos
Location Name: QB Energy SHAEFFER 31-6 (H-36) Pad
Location ID: 334904



Photo # 1952 Location



Photo # 1953 Location

Inspection/Audit Photos
Location Name: QB Energy SHAEFFER 31-6 (H-36) Pad
Location ID: 334904



Photo # 1954 Location

Photo # 1955 Location

Inspection/Audit Photos
Location Name: QB Energy SHAEFFER 31-6 (H-36) Pad
Location ID: 334904



Mar 10, 2025 at 1:20:43 PM
CO



Mar 10, 2025 at 1:19:59 PM
CO

Photo # 1956 Location

Photo # 1957 Location

Inspection/Audit Photos
Location Name: QB Energy SHAEFFER 31-6 (H-36) Pad
Location ID: 334904



Photo # 1958 Location



Photo # 1959 Location

Inspection/Audit Photos
Location Name: QB Energy SHAEFFER 31-6 (H-36) Pad
Location ID: 334904



Photo # 1960 Location



Photo # 1961 Battery lacks required signage

Inspection/Audit Photos
Location Name: QB Energy SHAEFFER 31-6 (H-36) Pad
Location ID: 334904



Photo # 1962 Battery lacks required signage

Photo # 1963 Battery lacks required signage