

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC Reppo/B Pad

Location ID: 334431

Date: 03/6/2025



Photo # 6613 Entrance to location



Photo # 6631 Battery sign contains inaccurate information/does not comply with CECMC rules

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC Reppo/B Pad

Location ID: 334431

Date: 03/6/2025



Photo # 6614 Location



Photo # 6623 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC Reppo/B Pad

Location ID: 334431

Date: 03/6/2025



Photo # 6626 Location



Photo # 6628 Location



Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC Reppo/B Pad

Location ID: 334431

Date: 03/6/2025



Photo # 6630 Location



Photo # 6650 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC Reppo/B Pad

Location ID: 334431

Date: 03/6/2025



Photo # 6638 SW corner of location



Photo # 6639 NW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC Reppo/B Pad

Location ID: 334431

Date: 03/6/2025



Photo # 6641 NE corner of location



Photo # 6642 SE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC Reppo/B Pad

Location ID: 334431

Date: 03/6/2025



Photo # 6644 Debris



Photo # 6655 Debris