

# Inspection Photos

API: 071-08801

Operator: OGRIS OPERATING LLC

Inspection Date: 3/10/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast along the access road..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** Facing northeast overlooking the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:071-08801 | Date: 3/10/2025

## Inspection Photos



**Photo 3.** Facing northeast along the cut slope.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources