

# Inspection Photos

API: 071-07428

Operator: OGRIS OPERATING LLC

Inspection Date: 3/10/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos



**Photo 1.** Facing west toward the wellsite.



Inspection Photos



**Photo 2.** Facing toward the produced water pit.



Inspection Photos



**Photo 3.** There is oily fluids in the engine skid that needs to be cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources