

Inspection Photos

API: 071-08085

Operator: OGRIS OPERATING LLC

Inspection Date: 3/10/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-08085 | Date: 3/10/2025

Inspection Photos



Photo 2. Facing toward the fill slope with a rip/rap stormwater outlet..



Inspection Photos



Photo 3. There is oily fluids in the engine skid that needs to be cleaned up.

