

Inspection Photos

March 5th, 2025

Operator: Logos Operating - 10679

Location ID: 325222

Inspection Document #: 714001917

La Plata County, CO

Township: SWNW 15 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ignacio 33-8 14
Location ID: 325222



Photo 1. View of project area from the eastern and southern edges facing center. Location has not been reclaimed to 1004 rules/standards. Surface owner equipment preventing establishment of desirable vegetation on location.

Inspection Photos
Location Name: Ignacio 33-8 14
Location ID: 325222

3/5/25
65° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Location access road has not been reclaimed to 1004 rules/standards.

API #: 067-05721