

**Inspection Photos**  
**Location Name: Amoco Energy Smits Unit C1**  
**Location ID: 311287**



**Photo 1 Location**



**Photo 2 Wellhead sign.**



**Inspection Photos**  
**Location Name: Amoco Energy Smits Unit C1**  
**Location ID: 311287**



**Photo 3 Wellhead.**



**Photo 4 Ancillary equipment.**

**Inspection Photos**  
**Location Name: Amoco Energy Smits Unit C1**  
**Location ID: 311287**




**Photo 5 Tank battery Location.**



**Photo 6 Tank battery sign.**



**Inspection Photos**  
**Location Name: Amoco Energy Smits Unit C1**  
**Location ID: 311287**



**Photo 7 Tank battery..**



**Photo 8 Gas Meter Run.**

**Inspection Photos**  
**Location Name: Amoco Energy Smits Unit C1**  
**Location ID: 311287**



**Photo 9 flow line manifold.**



**Photo 10 Horizontal Heated separator.**