

Inspection Photos
Location Name: Frank Trust 14-36H
Location ID: 421477



Photo 1 – Pumping Unit



Photo 2 – Well Sign

Inspection Photos
Location Name: Frank Trust 14-36H
Location ID: 421477



Photo 3 – Pumping Unit




Photo 4 – Wellhead

Inspection Photos
Location Name: Frank Trust 14-36H
Location ID: 421477



Photo 5 – Heater Treater and ECD



Photo 6 – Compressor

Inspection Photos
Location Name: Frank Trust 14-36H
Location ID: 421477



Photo 7 – Tank Battery



Photo 8 – Tank Battery Sign