

# Inspection Photos

03/7/2025

**Operator:** LARAMIE ENERGY LLC #10433

**Location ID:** 432260

**Inspection Doc:** 718100291

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 432260



**Photo 1:** Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 432260



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 432260



**Photo 3:** Photo example of vegetation establishment within the southern interim areas of the Location. Vegetation is predominantly shrubby species such as 4-wing saltbrush.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 432260



**Photo 4:** Photo of sediment trap on the southeastern working pad surface, and southern interim areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 432260



**Photo 5:** Photos shows sediment trap and outlet on the western working pad surface.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 432260



**Photo 6:** Photo taken from the interim areas on the north end of the Location, facing west. Vegetation established are predominantly wheatgrass species.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 432260



March 7, 2025

**Photo 7:** Photos examples showing the adjacent reference area vegetation. Species are predominantly shrubs (Sage brush). It is noted that the species observed establishing within the interim areas are not reflective of the adjacent reference areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 432260



**Photo 8:** Photos 8-10 examples showing Undesirable Plant Establishment (*Salsola* sp., Canada thistle) and weed debris on the working pad surface. Additional and ongoing weed management efforts to keep Location free of Undesirable Plant Species will be needed during the 2025 growing season. Weed debris requires removal and proper disposal.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 432260



**Photo 9:** See comments under photo 8.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 432260



**Photo 10:** See comments under photo 8.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources